


जावक क्र. तांत्रिक/प्रमाणपत्र/ 904 / 2024	सहाय्यक अभियंता (श्रेणी-१) यांचे कार्यालय सार्वजनिक बांधकाम उपविभाग सावनेर
email id :- saoner.de@mahapwd.gov.in	दिनांक:- 09/08/2024

प्रति,
मा. प्रिंसीपाल
इंडो अरविंद पब्लिक स्कूल
हेटी (सुरला) ता. सावनेर
जि. नागपूर


विषय:- इमारत सुरक्षित असल्याचे प्रमाणपत्र देण्याबाबत.
संदर्भ:- आपले कार्यालयीन पत्र क्र. AIPS/2025-26/Aff-2 Dated 29.03.2025


उपरोक्त संदर्भीय विषयाच्या अनूषंगाने मागणी केल्यानूसार शाळेची मौका
चौकशी करण्यात आली असून या पत्रासोबत वर्ष २०२५-२६ करिता इमारत सुरक्षित
असल्याचे प्रमाणपत्र (Building Safety Certificate) सादर करण्यात येत आहे.

सहपत्र :- इमारत सुरक्षित
असल्याचे प्रमाणपत्र


S. H. Damane
Assistant Engineer (Gr-1)
P.W. Sub Division Officer
सावनेर

प्रतिलिपी:- मा.कार्यकारी अभियंता सा. बां. विभाग क्र. नागपूर यांना माहितीकरिता
सविनय सादर.


Principal
Arvind Indo Public School
Hati (S.), Saoner-441107



Building Safety Certificate

to be field by the inspecting officer (Assistan Engineer Gr.I)
(Ref. G.O. Ms. 20/70/PWD Dt. 13.01.1970)

- 1) Name of Officer :- Assiatant Engineer (Gr.I) Public Works Sub Division,
Saoner Distt. Nagpur.
- 2) Name of the School :- Arvind Indo Public School, Heti (Surla) Tah- Saoner
Distt. Nagpur.
- 3) Location with name of Education Distt.sub Distt. :- Mouza Heti (Surla) Tah. Saoner Distt. Nagpur
- 4) Clasification of Building as :- R.C.C. Fame Structure
Specified in 4 Column of the G. F. 3.60 Mt. Height (2018-19)
Application for the Fitness F. F. 3.60 Mt. Height (2018-19)
Certificate and size S. F. 3.60 Mt. Height (2018-19)
- 5) Period of Which the Certificate :- 2025-2026
- 6) Nature of Defects, if any
 - a) Foundation and Basement :- No any defects occure
 - b) Super Structure :- No any defects occure
 - c) Door and Windows :- No any defects occure
 - d) Wood Work wrought and put up :- No any defects occure
 - e) Roof :- No any defects occure
 - f) Flooring :- No any defects occure
 - g) Miscellaneous (Crackes etc. :- No any defects occure
- 7) Any majoe defects noticed which will render the building unsafe if any manner. :- No
- 8) Whether mintenance works have been done properly :- Seen
- 9) Whether the Structure is Sound or not conducting classes :- **Structure is in Good Condition**

Note: 1. The Stability of the structure should be examined also with reference. antitude, intensity of wind, exposure of flood cte.
2. Any additional observation if deemed necessary for certificate may be furnished seperately with this certificate.

CERTIFICATE

Certified that the structure of building was inspected by me on Dt. 01.04.2025 and Found to be Fit to conduct classes for the period 2025-2026. for the reason stated above. Necessary Certificate regarding Electrification Firness and Fire fighting provision as per Building Code should be obtained by owner of Building.

Saoner

Date:- 01.04.2025

Principal

Arvind Indo Public School
Heti (S.), Saoner-441107

Assistant Engineer (Gr.I)
Public Works Sub Division
Saoner
P.W. Sub Division, Saoner

